


			<b>20</b>	4	Raccord M12 gaz
			<b>19</b>	1	Plaque d'aspiration
<b>39</b>	2	Circlips	<b>18</b>	1	Couvercle
<b>38</b>	1	Rondelle diam 20 ep 4	<b>17</b>	1	Pincage raccord
<b>37</b>	1	Ecrou H M6	<b>16</b>	1	Coude orientable
<b>36</b>	1	Ecrou H M8	<b>15</b>	1	Pincage support ventouse
<b>35</b>	4	Vis H M8x30	<b>14</b>	1	Plot plastique
<b>34</b>	4	Vis H M6x16	<b>13</b>	1	Butée
<b>33</b>	1	Vis H M6x30	<b>12b</b>	1	Entretoise diam 20 l 62
<b>32</b>	2	Vis CHC M8x40	<b>12a</b>	3	Entretoise diam 20 l 72
<b>31</b>	2	Vis FHC M8x20	<b>11</b>	1	Support entretoise
<b>30</b>	1	Vis H M8x35	<b>10</b>	1	Maneton
<b>29</b>	2	Vis FHC M8x40	<b>9</b>	1	Axe de rotation
<b>28</b>	1	Vis CHC M8x40	<b>8</b>	2	Coussinet
<b>27</b>	1	Vis FHC M8x20	<b>7</b>	1	Pavé de guidage
<b>26</b>	2	Vis FHC M6x20	<b>6</b>	1	Embout à rotule
<b>25</b>	4	Vis FHC M6x20	<b>5</b>	1	Axe vérin
<b>24</b>	2	Vis CHC M6x10	<b>4</b>	1	Vérin diam 20 course 50
<b>23</b>	2	Vis CHC M6x20	<b>3</b>	1	Chape
<b>22</b>	4	Embase ventouse	<b>2</b>	1	Support vérin
<b>21</b>	4	Ventouse	<b>1</b>	1	Plaque support
<b>Rep</b>	<b>Nb</b>	<b>Désignation</b>	<b>Rep</b>	<b>Nb</b>	<b>Désignation</b>

L.P. Alfred Costes 93000

ENCAISSEUSE  
PARTIE ROTATIVE  
PERSPECTIVE



DT1