



6,8pF C2
22pF C3

13V → 0,1 C10
L06
0,1 C11
150 R4
6,12 C12
100pF T1
BF245
1000pF C5
68k R3
330 PF C8
4,70 R5
82pF C13
100k R14
R6 2,70
R9 680
4,7nF C16
2,2R

0,01 C14
1k R7
2,7k R8
RH 680
4,7nF C17
100 R12
R13 220
13V ← C19

4,7k R1
BB 205 D1
2 PF C1
L
100pF C6
BB109
D2
R2 100k
C4 10nF (0,01)
V Vers R9 (100k)

100pF C6
BB109
D2
R2 100k
C7 4,7nF
10k ou 5k (10t)
10 4F
1k (Fin) (5 ou 10t)
1k

10V L10
0,1
0,1