

STARBUCK

LITTLE GOOSE LOCK AND DAM (16W) 7 NE UTC-8(-7DT) N46°35.04' W118°00.22'

SEATTLE

681 NOTAM FILE SEA

RWY 07-25: 3400X50 (GRVL)

RWY 07: Road.

RWY 25: Hill.

AIRPORT REMARKS: Unattended. Do not land if snow present on rwy. No winter snow removal ops. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acct accidents/incidents ctc WA state emergency operations center 800-258-5990. Arpt lctd in canyon, rolling terrain 700-800' south rising to 750', canyon wall 800' south rises steeply to 1800'+, north wall rises to 1600'+. Density altitude. High terrain surrounds arpt. Strong winds possible inside canyon. Pedestrians, vehicles, and animals on and invof rwy. Portions of rwy sfc rough and soft. Rwy marked with reflectors dur dates arpt is open.

AIRPORT MANAGER: (360) 618-2477**COMMUNICATIONS:** CTAF 122.9

STEHEKIN STATE (6S9) 3 NW UTC-8(-7DT) N48°20.75' W120°43.25'

SEATTLE

1230 NOTAM FILE SEA

RWY 13-31: 2630X100 (TURF) 1.5% up NW

RWY 13: Trees.

RWY 31: Brush.

AIRPORT REMARKS: Unattended. Arpt CLOSED 1 Oct—1 Jun exc for apvd mil and public safety/law enforcement helicopter ops. No mil use dur clsd periods exc emerg. Pedestrians, vehicles and animals on and invof rwy. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acct accidents/incidents ctc WA state emergency operations center 800-258-5990. Rwy marked with reflectors dur dates arpt is open.

AIRPORT MANAGER: (360) 618-2477**COMMUNICATIONS:** CTAF 122.9

STROM FLD (See MORTON on page 189)

SULLIVAN LAKE STATE (See METALINE FALLS on page 189)

SULTAN

SKY HARBOR (S86) 1 E UTC-8(-7DT) N47°52.24' W121°47.54'

SEATTLE

282 NOTAM FILE SEA

RWY 07-25: 1930X100 (TURF)

RWY 07: Brush.

RWY 25: Brush.

AIRPORT REMARKS: Unattended. Ctc arpt mgr 425-359-4625 for facility info prior to use. Watch for animals and children on and invof arpt. West end very soft in winter and spring. Preferred rwy ops wind permitting land west, tkf east. Avoid arpt dur high wind conditions. No touch and go ops. No instr or student ops. Helicopter parking northeast end of rwy.

AIRPORT MANAGER: 425-359-4625**COMMUNICATIONS:** CTAF 122.9 UNICOM 122.8

SUNNYSIDE MUNI (1S5) 2 E UTC-8(-7DT) N46°19.63' W119°58.22'

SEATTLE

768 B NOTAM FILE 1S5

RWY 07-25: H3423X60 (ASPH) S-12.5 LIRL 0.6% up E

RWY 07: PAPI(P2L)—GA 3.0°. Road.

RWY 25: PAPI(P2L)—GA 3.0°. Pole.

SERVICE: FUEL 100LL**AIRPORT REMARKS:** Unattended.**AIRPORT MANAGER:** 509-837-5206**WEATHER DATA SOURCES:** AWOS-3PT 123.675 (509) 836-2384.**COMMUNICATIONS:** CTAF 122.9**RADIO AIDS TO NAVIGATION:** NOTAM FILE PSC.

PASCO (L) VOR/DME 109.8 PSC Chan 35 N46°16.22'

W119°07.04' 261° 35.7 NM to fld. 406/15E.

DME unusable:

160°-170° byd 30 NM

L-13A

