

ABBOTSFORD (CYXX) 2 SW UTC-8(-7DT) N49°01.52' W122°21.60'

SEATTLE
H-18, L-1E

194 B AOE NOTAM FILE CYXX Not insp.

RWY 07-25: H9597X200 (ASPH-CONC) HIRL

RWY 07: SSALR. REIL. Rgt tfc.

RWY 25: ODALS. REIL. PAPI(P4L)—GA 3.0°. Thld dspcd 295'.

RWY 01-19: H5328X200 (ASPH) MIRL

RWY 01: REIL. PAPI(P4L)—GA 3.0°. Rgt tfc.

RWY 19: REIL. PAPI(P4L)—GA 3.0°.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 01: TORA-5328 TODA-6178 ASDA-5328 LDA-5328

RWY 07: TORA-9597 TODA-10101 ASDA-9597 LDA-9597

RWY 19: TORA-5328 TODA-5854 ASDA-5328 LDA-5328

RWY 25: TORA-9597 TODA-10581 ASDA-9695 LDA-9302

SERVICE: S4 FUEL 100LL, JET A

AIRPORT REMARKS: Attended continuously. ARFF svc avbl. Turbo-jet, turbo-fan, and turbo-prop not permitted from 0600-1500Z†. All other ngt trng as authorized by arpt mgr. Parachute area aprx 5 NM NE of arpt. Prior ntc rqrd for cstm (1600-0800Z†) call 888-226-7277. IFR trng fits PPR ctc 604-775-9674. Helicopter trng on inflid. Numerous obst in helicopter trng areas. Oprs ltd winter maintenance 1430-0700Z†. Other times 2 hrs prior ntc rqrd, call out charge. PPR dur winter maintenance exc scheduled ops, alternate or emerg, CRFI, PLR/PCN. Turf rwy clsd exc with prior permission and agreement plan with arpt mgr. Tall vehicles on road south of thld Rwy 01. Ltd parking and deicing dur winter ops, all wide body acft 24 hr prior ntc ctc ops 604-864-5544. Transit parking rstd to Apron 1. All other parking PPR ctc ops. Apron 1 north of Twy B, including Twy A, ltd to acft with wingspans of 118' or less. PPR for larger acft. Twy D unctl exc of blast fence. Turns from Twy A onto Twy C rstd to C-130 smaller (blast issue). Rwy 01-19 and Twy B not avbl for acft taxiing when RVR below 2600'. Night ops must use PAPI.

COMMUNICATIONS: ATIS 119.8 (1500-0700Z†) 877-517-2847

ABBOTSFORD RADIO (CYXX) on arpt 122.5

VICTORIA TERMINAL APP/DEP CON 132.7

TOWER 119.4 (inner) 121.0 (outer) (1500-0700Z†) Mandatory freq 119.4 (0700-1500Z† below 4500' MSL)

GND CON 121.8 (1500-0700Z†)

RADIO AIDS TO NAVIGATION: NOTAM FILE BLI.

WHATCOM (H) VORTACW 113.0 HUH Chan 77 N48°56.72' W122°34.76' 041° 9.9 NM to fld. 83/20E. **HIWAS.**

TACAN AZM unusable:

155°-165° byd 15 NM blo 6,000'

NDB (HW) 344 XX N49°00.93 W122°29.27 068° 4.3 NM to fld. /19E.

WHITEROCK NDB (MHW) 332 WC N49°00.20 W122°45.02 067° 14.7 NM to fld. /19E.

CULTUS NDB (HW) 214 LU N49°01.27 W122°02.98 252° 12.3 NM to fld.

ILS 109.7 I-1XX Rwy 07

COMM/NAV/WEATHER REMARKS: Local call to ABBOTSFORD FSS dial 604-852-2781.

AJ EISENBERG (See OAK HARBOR on page 191)

AMERICAN LAKE SPB (See TACOMA on page 213)

ANACORTES

ANACORTES (74S) 2 W UTC-8(-7DT) N48°29.91' W122°39.75'

SEATTLE
L-1E

241 B LRA NOTAM FILE SEA

RWY 18-36: H3015X60 (ASPH-GRVD) S-12.5 MIRL 0.3% up S

RWY 18: REIL. PAPI(P4R)—GA 3.0° TCH 40'. Trees. Rgt tfc.

RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Trees.

SERVICE: S4 FUEL 100, JET A **LGT** ACTIVATE MIRL and REIL Rwy 18 and Rwy 36—CTAF.

AIRPORT REMARKS: Unattended. Mil arr corridor north and west of arpt. No touch and go lds. NS ABTMT procedures in effect, ctc arpt mgr 360-293-3134. Rwy 36 preferred calm wind rwy.

AIRPORT MANAGER: 360-293-3134

COMMUNICATIONS: CTAF 128.25

RADIO AIDS TO NAVIGATION: NOTAM FILE BLI.

WHATCOM (H) VORTACW 113.0 HUH Chan 77 N48°56.72'

W122°34.76' 167° 27.0 NM to fld. 83/20E. **HIWAS.**

TACAN AZIMUTH unusable:

155°-165° byd 15 NM blo 6,000'

